

HOBART BROTHERS CO -- HOBART 418 -- 3439-01-039-3494

=====
Product Identification
=====

Product ID:HOBART 418

MSDS Date:02/01/1992

FSC:3439

NIIN:01-039-3494

MSDS Number: BNKCR

=== Responsible Party ===

Company Name:HOBART BROTHERS CO

Address:600 W MAIN ST

City:TROY

State:OH

ZIP:45373

Country:US

Info Phone Num:513-332-4000

Emergency Phone Num:513-332-4000

CAGE:28835

=== Contractor Identification

===

Company Name:HOBART BROTHERS CO

Address:600 W MAIN ST HOBART SQUARE

Box:City:TROY

State:OH

ZIP:45373

Country:US

Phone:513-339-6000

CAGE:28835

=====
Composition/Information on Ingredients
=====

Ingred Name:IRON

CAS:7439-89-6

RTECS #:NO4565500

Fraction by Wt: 60-100%

OSHA PEL:5 MG/CUM RESPIRABLE

ACGIH TLV:10 MG/CUM

Ingred Name:MANGANESE, MN COMPOUNDS

CAS:7439-96-5

RTECS #:OO9275000

Fraction by Wt: 1-5%

OSHA PEL:5 MG/CUM (DUST)

ACGIH TLV:5 MG/CUM (DUST)

Ingred Name:CALCIU

ion =====

Routes of Entry: Inhalation:YES Skin:YES Ingestion:NO
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO
Health Hazards Acute and Chronic:INHALATION: SIDEROSIS, PULMONARY
EDEMA, BRONCHITIS. MANGANESE CAN CAUSE METAL FUME FEVER. ARC RAYS
CAN INJURE/BURN SKIN & EYES. LONG TERM EXPOSURE: BRONCHIAL ASTHMA,
LUNG FIBROSIS, SIDEROSIS, MANGANIS M, OSTEOPOROSIS, MOTTILING OF
TEETH, DERMATITIS, PNEUMONIA.

Explanation of Carcinogenicity:NONE

Effects of Overexp

osure:INHALATION: DISCOMFORT, DIZZINESS, NAUSEA,
DRYNESS, NOSE/THROAT/EYES IRRITATION, NASAL SEPTUM PERFORATION,
MUSCLE WEAKNESS, TREMORS. METAL FUME FEVER: CHILLS, FEVER, UPSET
STOMACH, VOMITING, THROAT IR RITATION, BODY ACHES. SKIN:
IRRITATION,ULCERATION.

===== First Aid Measures =====

First Aid:EMPLOY FIRST AID TECHNIQUES RECOMMENDED BY THE AMERICAN RED
CROSS. EYES/SKIN: IF IRRITATION OR FLASH BURNS DEVELOP AFTER
EXPOSURE, CONSUL
T A PHYSICAN. OBTAIN MEDICAL ATTENTION IN ALL
CASES.

===== Fire Fighting Measures =====

Unusual Fire/Explosion Hazard:NON FLAMMABLE. WELDING ARC & SPARKS CAN
IGNITE COMBUSTIBLES.

===== Handling and Storage =====

Handling and Storage Precautions:ELECTRIC SHOCK CAN KILL. TRAIN THE
WELDER NOT TO TOUCH LIVE ELECTRICAL PARTS, TO INSULATE HIMSELF FROM
WORK/GROUND, & TO KEEP HIS HEAD OUT OF FUMES.

Other Precautions

:ONE RECOMMENDED WAY TO DETERMINE THE COMPOSITION &
QUANTITY OF FUMES & GASES TO WHICH WORKERS ARE EXPOSED IS TO TAKE
AN AIR SAMPLE INSIDE THE WELDER'S HELMET IF WORN OR IN THE WORKER'S
BREATHING ZONE.

===== Exposure Controls/Personal Protection =====

Respiratory Protection:USE NIOSH APPROVED OR EQUIVALENT/AIR SUPPLIED
RESPIRATOR WHEN WELDING IN CONFINED SPACE.

Ventilation:LOCAL EXHAUST AT THE ARC TO KEEP