

GENERAL ELECTRIC CO GE LIGHTING -- F15T8D FLUORESCENT LAMP -- 6240-00-152-2992

=====
Product Identification
=====

Product ID:F15T8D FLUORESCENT LAMP

MSDS Date:02/03/1992

FSC:6240

NIIN:00-152-2992

MSDS Number: BYVTX

=== Responsible Party ===

Company Name:GENERAL ELECTRIC CO GE LIGHTING

Address:1975 NOBLE RD; NELA PARK NO 4310

City:CLEVELAND

State:OH

ZIP:44112

Country:US

Info Phone Num:216-266-3349

/800-624-0624

Emergency Phone Num:216-266-2121

CAGE:08805

=== Contractor Identification ===

Company Name:GENERAL ELECTRIC CO GE LIGHTING

Address:NELA PARK NO 4705

Box:City:CLEVELAND

State:OH

ZIP:44112

Country:US

Phone:800-624-0624/216-266-2121

CAGE:08805

=====
Composition/Information on Ingredients
=====

Ingred Name:GLASS, SODA-LIME (GLASS TUBE)

Other REC Limits:NONE RECOMMENDED

Ingred Name:MERCURY, ELEMENTAL (AMT IN FLUORESCENT LAMP IS ROUGHLY
PROPORTIONAL TO ITS LENGTH

,BEING ABOUT 5-10 MILLIGRAMS/FOOT)

CAS:7439-97-6

RTECS #:OV4550000

Fraction by Wt: SEE ING

Other REC Limits:NONE RECOMMENDED

EPA Rpt Qty:1 LB

DOT Rpt Qty:1 LB

Ingred Name:ATMOSPHERE OF INERT GAS (USUALLY ARGON, NEON OR KRYPTON)

Other REC Limits:NONE RECOMMENDED

Ingred Name:PHOSPHOR (RELATIVELY INERT PHOSPHATE THAT HAS BEEN USED BY
GE CO SINCE 1949).

Other REC Limits:NONE RECOMMENDED

=====
Hazards Identification
=====

Health Hazards Acute and Chronic:INCI

DENTAL EXPOSURE TO INERT PHOSPHATE

DUE TO BROKEN LAMP HAS BEEN FOUND TO BE NOT HARMFUL.NO SIGNIFICANT ADVERSE EFFECTS EITHER BY INGEST/INHAL/SKIN CONTACT/EYE IMPLANT WERE FOUND IN 5YR ANIMAL STUDY OF ORIGNIAL PHOSPHOR BY INDUST HYG FOUND OF MELLON INST.TO GE KNOWLEDGE THERE HAVE BEEN NO SIGNIFICANT (SIGNS/SYMPTOMS)

Effects of Overexposure:HEALTH HAZ:ADVERSE EFFECTS ON HUMANS BY ANY OF THESE ROUTES DURING THE MANY YRS OF ITS MFG/USE.

Medical Cond Aggravated by Exposure:NO
NE SPECIFIED BY MANUFACTURER.

=====
First Aid Measures
=====

First Aid:NONE SPECIFIED BY MANUFACTURER.

=====
Fire Fighting Measures
=====

Extinguishing Media:MFG NOT PROVIDED. HMIS:USE APPROPRIATE FIRE EXTINGUISHING MEDIA FOR SURROUNDING FIRE.

Fire Fighting Procedures:MFG NOT PROVIDED. HMIS:USE APPROPRIATE PPE AS CONDITIIONS WARRANT.

=====
Accidental Release Measures
=====

Spill Rele

ase Procedures:AS IN CASE OF PROD CONTAINING GLASS/CHEM

REASONABLE CARE SHOULD BE OBSERVE WHEN BURNED OUT FLUORESCENT LAMPS HNDLD/DISCARDED.FLUORESCENT LAMPS FILLED TO VERY LOW PRESSURE(ALMOST VAC);IMPLOSIONS MAY OC CUR IF BROKEN.PROPER EQMT SHOULD BE WORN (SUPPLE)

Neutralizing Agent:NONE SPECIFIED BY MANUFACTURER.

=====
Handling and Storage
=====

Handling and Storage Precautions:FLUORESCENT LAMPS CONTAIN RELATIVELY SM QUANT OF MERCURY;AMT ROUGHLY PROPORTIONAL TO LAMP'S LENGTH-ABOUT 5-10MG OF MERCURY/FT.DISPOSAL MAYBE REGULATED

Other Precautions:INFO FOR THIS MSDS TAKEN FROM PRODUCT SHEETS FAXED FROM GE LIGHING.ITEM IS ARTICLE;LOW PRESSRUE DISCHARGE LAMPS.ELECTRIC ARC CONDUCTED THRU ATM OF INERT GAS & MERCURY VAP.LIGHT GENERATED BY THIN PHOSP HOR COAT ON INSIDE SURFACE OF TUBE.

=====
Exposure Controls/Personal Protection
=====

Respiratory Protection:SUITABLE RESPIRATORS SHOULD BE WORN IF ME

RCURY

VAP CONCEN EXCEEDS EXTABLISHED STDS WHEN LG QUANT OF LAMPS ARE
BROKEN (ESPECIALLY IN CONFINED OR POORLY VENTILATED AREA).

Ventilation:INCREASED VENTILATION FOR LG QUANT OF BROKEN LAMPS
RESULTING IN MERCURY VAP CONCEN EXCEEDS ESTABLISHED STDS.

Work Hygienic Practices:MFG NOT PROVIDED. HMIS:USE CAUTION WHEN
HANDLING LAMPS & WHEN BROKEN.

Supplemental Safety and Health

SPILL:WORN TO PROT EYE/SKIN FROM FLYING GLASS FRAGMENTS.LG QUANT OF
FLUORESCENT LAMPS BROKEN-PRECAUT MEASU

RES RECOMMENDED TO CNTRL EXPO

TO DISPERSED DUST/MERCURY VAP.BREAK OUTDOORS/WELL VENT INDOOR AR
EA.USE CLSD WASTE CNTNR/LOC VENT. DISPO:IF LG QUANT,MEASURE PERDCLY
MERCURY VAP CONCEN.LEVELS EXCEED USE PPE.MAY BE REG.

===== Physical/Chemical Properties =====

HCC:N1

Appearance and Odor:ARTICLE.

===== Stability and Reactivity Data =====

Stability Condition to Avoid:MFG NOT PROVIDED. HMIS:BROKEN FLUORESCENT
LAMPS.

=====

===== Disposal Considerations =====

Waste Disposal Methods:MAY BE REGULATED.DON'T THROW LAMPS INTO
FIRE/DOMESTIC-TYPE INCINERATOR.IN MOST CASES OF BROKEN LAMP,NOT
EXPECT THE SM AMT OF MERCURY PRESENT WILL CAUSE ANY SIGN AMT OF
AIRBORNE MERCURY SINCE MOST OF E LEMENTAL MERCURY REMAINS ADHER TO
PHOSHPOR(SUPPLY)

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Department
of Defen

se. The United States of America in no manner whatsoever,
expressly or implied, warrants this information to be accurate and
disclaims all liability for its use. Any person utilizing this
document should seek competent professional advice to verify and
assume responsibility for the suitability of this information to their
particular situation.