View NSN Online: https://aerobasegroup.co.il/nsn/5910-00-243-6380

CORNELL-DUBILIER ELECTRONICS DIV FED PACIFIC ELEC -- KGBT6037 -- 5910-00-243-6380

Product ID:KGBT6037 MSDS Date:01/01/1985

FSC:5910

NIIN:00-243-6380

MSDS Number: BDMYC === Responsible Party ===

Company Name: CORNELL-DUBILIER ELECTRONICS DIV FED PACIFIC ELEC

Address: ONE INTERCHANGE PLZ

City:WAYNE State:NJ ZIP:07470 Country:US

Emergency Phone Num: NONE

CAGE:14655

=== Contractor Identification ===

Company Name: CORNELL-DUBILIER ELECTRONICS

Address: ONE INTERCHANGE PLZ

Box:City:WAYNE

State:NJ ZIP:07470 Country:US

Phone:201-694-8600

CAGE:14655

======= Composition/Information on Ingredients ========

Ingred Name: POLYCHLORINATED BIPHENYLS (PCBS) (SARA III)

CAS:1336-36-3

RTECS #:TQ1350000 EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

Effects of Overexposure: ABSORBED THRU SKIN, LUNGS, INTESTI

CANCER, LIVER, KIDNEY, STOMACH, EYE, HEARING DISORDER (SUP DATA)
======================================
First Aid:EYES:FLUSH W/WATER IMMED.SKIN:WASH W/SOAP IMMED.INHAL:REMOVE TO FRESH AIR.GIVE ART.RESPIR. AS NEEDED.INGEST:GET MEDICAL ATTN.GIVE LARGE QTY OF SALT WATER,INDUCE VOMITING,BUT DO NOT MAKE UNCONSCIOUS PE RSON VOMIT.
======== Accidental Release Measures =========
Spill Release Procedures:USE ABSORBENT & DIKES TO P REVENT
RUNOFF.ISOLATE & NOTIFY PROPER AUTHORITIES.
========== Handling and Storage ============
Handling and Storage Precautions:STORAGE MUST FOLLOW RCRA REQUIREMENTS.
====== Exposure Controls/Personal Protection ========
Respiratory Protection:SUPPLIED AIR W/FULL FACEPIECE,HELMET OR HOOD Ventilation:LOCAL EXHAUST Protective Gloves:RUBBER-IMPERV Eye Protection:GOGGLES,FACE SHIELD Other Protective Equipment:FULL CLOTHING TO PREVENT SKIN CONTACT Supplem ental Safety and Health OVEREXPOS:CAN CAUSE FORMATION OF CYSTS.CAUSES STILLBIRTHS.IRRITATES EYES,NOSE,THROAT.
======== Physical/Chemical Properties =========
HCC:Z3 Appearance and Odor:LIGHT STRAW COLORED LIQUID,AROMATIC ODOR
========== Stability and Reactivity Data ==========
STRONG OXIDIZERS
======== Disposal Considerations ===========
Wasta Disposal Mathods:CONTROLLED DISPOSAL REQUIRED CENERALLY HIGH

NE.CAUSES

Waste Disposal Methods:CONTROLLED DISPOSAL REQUIRED-GENERALLY HIGH TEMPERATURE INCINER

ATION.ONLY APPROVED DISPOSAL OPERATOR PERMITTED.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitabilit y of this information to their particular situation.