View NSN Online: https://aerobasegroup.co.il/nsn/3439-00-803-9499

Product ID:#5554;ELECTRODE,WELDING

MSDS Date:01/01/1987

FSC:3439

NIIN:00-803-9499

MSDS Number: BFQDD === Responsible Party ===

Company Name: J.H.HARRIS CO. INC. Emergency Phone Num: 513-891-2000

CAGE:MO001

=== Contractor Identification ===

Company Name: J. W. HARRIS CO., INC.

Address:10930 DEERFIE

LD ROAD

Box:City:CINCINNATI

State:OH

ZIP:45242-4110

Country:US

Phone:513-891-2000

CAGE:27911

Company Name: J.H.HARRIS CO. INC.

CAGE:MO001

====== Composition/Information on Ingredients ========

Ingred Name: ALUMINUM (SARA III)

CAS:7429-90-5

RTECS #:BD0330000 Fraction by Wt: 95.3%

OSHA PEL:15MG/M3 DUST/5 FUME ACGIH TLV:10MG/M3 DUST; 9192

Ingred Name:TITANIUM DIOXIDE

CAS:13463-67-7 RTECS #:XR2275000 Fraction by Wt: 0.12%

OSHA PEL:15 MG/M3 TDUST

ACGIH TLV:10 MG/M3 TDUST; 9293

Ingred

CAS:1314-13-2 RTECS #:ZH4810000 Fraction by Wt: 0.25%
OSHA PEL:15MG/M3 TDUST/5 FUME ACGIH TLV:10MG/M3 TDUST; 9293
Ingred Name:CHROMIUM (SARA III) CAS:7440-47-3 RTECS #:GB4200000 Fraction by Wt: 0.12% OSHA PEL:1 MG/M3 ACGIH TLV:0.5 MG/M3; 9192 EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB
Ingred Name:MAGNESIUM OXIDE CAS:1309-48-4 RTECS #:OM3850000 Fraction by Wt: 2.7%
OSHA PEĹ:15 MG/M3 PARTICULATE ACGIH TLV:10 MG/M3;TDUST; 9293
======================================
Effects of Overexposure:INHALATION OF FUMES:SKIN & EYES IRRITATION;DIZZINESS,NAUSEA,IRRIT.OF THROAT;METAL FUME FEVER;CR:CARC
======================================
First Aid:INHALE:REMOVE TO FRESH AIR, GIVE CPR/O*2 IF NEED;EYES/SKIN:FLUSH W LG AMTS H*2O FOR 15 MIN;INGEST:RINSE MOUTH; GET MEDICAL ATTENTION FOR EYES, BREATHING DIFFICULTY, OR OTHER SYMPTOMS OF OVEREXPOSURE.
======================================
Flash Point:NONE Extinguishing Media:CO*2,DRY CHEM CA,FOAM Fire Fighting Procedures:USE NIOSH/MSHA APPROVED SCBA IN CONFINED AREA Unusual Fire/Explosion Hazard:WELDING ARC,OPEN FLAME AND SPARKS CAN IGNITE COMBUSTIBLES;USE REASONABLE CARE.
======== Accidental Release Measures ===========
Spill Release Procedures:USE PROPER PROTECTION:RECOVER SCRAP METAL OR RODS AND DISPOSE OF UNDER RULES
======================================
Hand

Name:ZINC OXIDE

ling and Storage Precautions: STORE IN DRY AREA. KEEP TIGHTLY CLOSED:HANDLE WITH FUL PERSONAL PROTECTION. Other Precautions: AVOID CONTACT WITH EYES AN SKIN: DO NOT BREATHE DUST/METAL FUMES: USE GOOD INDUSTRIAL HYGIENE PRACTICE. ===== Exposure Controls/Personal Protection ======== Respiratory Protection: USE NIOSH/MSHA APPROVED RESPIRATOR FOR DUST/METAL FUMES IF ABOVE TLV Ventilation:LOCAL EXHAUST TO MAINTN BELOW TLV. Protective Gloves:WELDER GLOVES Eve Protection: GOGGLES /FACE SHIELD Other Protective Equipment: FULL PROTECTIVE CLOTHING, SAFETY SHOWER, EYE WASH STATION Supplemental Safety and Health MSDS DATED; NOVEMBER, 1985: OTHER INGREDIENTS:MN=0.75%;COPPER=0.10%;FE=0.40%;S1=0.25% ======== Physical/Chemical Properties =========== HCC:N1 Solubility in Water: NEGLIGIBLE Appearance and Odor:SOLID WIRE OR ROD ======== Stability and Reactivity Data ========== Stability Indicator/Materials to Avoid:YES NONE NOTED Stability C ondition to Avoid:HEAT Hazardous Decomposition Products: METAL FUMES DURING WELDING,CO,CO\*2,O\*3,NITROGEN OXIDE. ======= Disposal Considerations ============

Waste Disposal Methods: DISPOSE OF COLLECTED MATERIAL IN ACCORDANCE WITH LOCAL STATE AND FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner wha

## tsoever,

expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.