View NSN Online: https://aerobasegroup.com/nsn/9150-01-102-5020

Product ID:WINSOR LUBE L-245X
MSDS Date:01/01/1987
FSC:9150
NIIN:01-102-5020
MSDS Number: BGLXG
=== Responsible Party ===
Company Name: ANDERSON OIL AND CHEMICAL COMPANY, INC.
Emergency Phone Num:203-342-0660
CAGE:J0782
=== Contractor Identification ===
Company Name:ALLIED-KELITE
Ad
dress:ONE BROWNSTONE AVENUE
Box:City:PORTLAND
State:CT
ZIP:06480
Country:US
Phone:203-342-0660
CAGE:70575
Company Name: ANDERSON OIL AND CHEMICAL COMPANY
CAGE:JO782
========= Composition/Information on Ingredients ====================================
Ingred Name:NONE SPECIFIED BY MFG.
RTECS #:9999999ZZ
Hozardo Identification
======================================
Effects of Overexposure:NONE RPT IN LIT. MAY IRRITATE EYES OR VERY

SENSE SKIN.

First Aid:INHAL:RMV TO FRESH AIR. IF NOT BRTHNG GIVE CPR; IF BRTHNG DIFF GIVE OXYGEN. EYE:IMMED FLUSH W/PLENTY OF WATER. SKIN:WASH W/SOAP & WATER. RMV CONTAM CLTHG & SHOES. INGEST:DO NOT INDUCE VOMIT. NOTHG BY MOUTH IF UNCONSC. GET MEDICAL ATTN.

Flash Point:435F, 224C COC Extinguishing Media:DRY CHEM, CO\*2, FOA, WATER FOG. Fire Fighting Procedures:DO NOT USE WATER EXCEPT AS FOG. Unusual Fire/Explosio

n Hazard:NONE
======================================
Spill Release Procedures:MOP OR WIPE UP SM AMT. ABSORB WITH INERT MATERIAL AND STORE IN CLOSED DISPOSA DRUMS
======================================
Handling and Storage Precautions:AVOID GENERATING MIST/FUMES Other Precautions:NONE
========= Exposure Controls/Personal Protection ====================================
Respiratory Protection:NOT MORMALLY REQ. USE NIOSH/MSHA APPROV SCBA FOR HOT FUMES/ENCL AREA Ventilation:MECHANICAL (GEN) RECOMMENDED. Protective Gloves:NEOPRENE Eye Protection:CHEM SPLASH GOGGLES Other Protective Equipment:USE CHEM RESIS APRON & OTHER CLTHNG TO AVOID PROLONG CONTACT Supplemental Safety and Health MSDS DATED AUGUST 20, 1985.

HCC:V6 Boiling Pt:B.P. Text:>500F,>260C Spec Gravity:0.92 Solubility in Water:SLIGHT Appearance and Odor:CLEAR RED-BROWN LIQUID, BLAND ODOR.

Stability Indicator/Materials to Avoid:YES STRONG OXIDIZING AGENTS Stability Condition to Avoid:NONE Hazardous Decomposition Products:SMOKE, CO, CO\*2

Waste Disposal Methods: INCINERATE IAW ALL LOCAL, STATE AND FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.