
View NSN Online: https://aerobasegroup.co.il/nsn/5330-00-024-2186 HERCULES ENGINES INC -- GASKET -- 5330-00-024-2186 Product ID:GASKET MSDS Date:12/22/1994 FSC:5330 NIIN:00-024-2186 MSDS Number: BWQYR === Responsible Party === Company Name: HERCULES ENGINES INC Address:101 11TH ST S E Box:24101 City: CANTON State:OH ZIP:44701-4101 Country:US Info Phone Num:216-454-5631 Emergency Phone Num:216-454-5631 CAGE:28265 === Contractor Identification === Company Name: HERCULES ENGINES INC Address:101 11TH ST S E Box:24101 City: CANTON State:OH ZIP:44701-4101 Country:US CAGE:28265 ======= Composition/Information on Ingredients ======== Ingred Name: ASBESTOS, CHRYSOTILE CAS:12001-29-5 RTECS #:CI6478500 Other REC Limits: NONE RECOMMENDED OSHA PEL:0.2 FIBERS/CC

ACGIH TLV:2 FIBERS/CC; A1;9394

=========== Hazards Identification ==========================

LD50 LC50 Mixture:TLV FOR ASBESTOS IS 2 FIBERS/CC

Routes o



CLEAN,DRY PLACE,AWAY FROM STRONG OXIDIZING AGENTS. NORMAL WASH UP AFTER HANDLING IS
RECOMMENDED. Other Precautions: ASBESTOS IS BONDED BY AN ELASTOMETER COMPOUND,
HOWEVER, DO NOT MISUSE BY IMPROPER CUTTING OR HANDLING.
====== Exposure Controls/Personal Protection ========
Respiratory Protection:NONE NORMALLY REQUIRED. IF FIBERS MAY BE RELEASED, USE NIOSH APPROVED HALF FACE RESPIRATOR WITH HEPA FILTERS.
Ventilation:NO SPECIAL REQUIREMENT UNDER NORMAL CONDITIONS . IF FIBERS
MAY BE RELEASED, USE LOCAL EXHAUST VENTILATION. Protective Gloves: NOT NORMALLY REQUIRED.
Eye Protection:SAFETY GLASSES. Other Protective Equipment:NONE SPECIFIED BY MANUFACTURER. Work Hygienic Practices:WASH THOROUGHLY AFTER HANDLING AND BEFORE EATING. LAUNDER CONTAMINATED CLOTHING BEFORE REUSE. Supplemental Safety and Health
HERCULES(MFR) WAS UNABLE TO PROVIDE THE REQUIRED MSDS.MSDS DATA PROVIDED BY MR. KURT W. MANTE, AT DEFENSE INDUSTRIAL CENTER. AS MANUFACTURED, LO
CKED-IN ASBESTOS DOES NOT PRESENT A HAZARD. ONLY WHEN THE ITEM IS SUBJECTED TO ABRASIVE ACTIONSAND DUST IS GENERATED, THEN ASBESTOS FIBERS MAY BE RELEASED AND BECOME AIRBORNE.
========= Physical/Chemical Properties =========
HCC:T6 Solubility in Water:INSOLUBLE Appearance and Odor:GASKET.
======== Stability and Reactivity Data =========
Stability Indicator/Materials to Avoid:YES NONE SPECIFIED BY MANUFACTURER. Stability Condition to Avoid:N ONE SPECIFIED BY MANUFACTURER. Hazardous Decomposition Products:ASBESTOS FIBERS.
======== Disposal Considerations ====================================
Waste Disposal Methods:CONTACT YOUR LOCAL ENVIRONMENTAL OFFICER. ASBESTOS DUST SHOULD BE WETTED AND VACUUMED UP WITH HEPA FILTERED VACUUM CLEANER,SEALED IN A PLASTIC BAG,AND TURNED IN TO DISPOSAL COMPANY.DISPOSE OF IN ACCOR DANCE WITH ALL LAWS AND REGULATIONS.

Di

sclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.