

HARDMAN INCORP. -- EPOWELD 8173 PART A -- 8040-00-092-2816

=====  
Product Identification  
=====

Product ID:EPOWELD 8173 PART A  
MSDS Date:09/24/1991  
FSC:8040  
NIIN:00-092-2816  
Kit Part:Y  
MSDS Number: BCYMD  
=== Responsible Party ===  
Company Name:HARDMAN INCORP.  
Address:600 CORTLANDT ST  
City:BELLEVILLE  
State:NJ  
ZIP:07109-3328  
Country:US  
Info Phone Num:201-751-3000  
Emergency Phone Num:201-751-3000  
Prepa  
rer's Name:JAMES T. SCHIRRIPA  
CAGE:KO053  
=== Contractor Identification ===  
Company Name:HARDMAN INC  
Address:600 CORTLANDT ST  
Box:City:BELLEVILLE  
State:NJ  
ZIP:07109-3328  
Country:US  
Phone:201-751-3000  
CAGE:96900  
Company Name:HARDMAN INCORP.  
Address:600 CORTLANDT ST  
Box:City:BELLEVILLE  
State:NJ  
ZIP:07109-3328  
Country:US  
Phone:201-751-3000  
CAGE:KO053

=====  
Composition/Information on Ingredients  
=====

Ingred Name:EPICHLOROHYDRIN (SARA III)  
CAS:106-89-8  
RTECS #:TX4900000  
OSHA PEL:

S, 5 PPM  
ACGIH TLV:S, 2 PPM; 9293  
EPA Rpt Qty:100 LBS  
DOT Rpt Qty:100 LBS

=====  
Hazards Identification  
=====

Effects of Overexposure:PROLONGED OR REPEATED CONTACT MAY CAUSE SKIN & EYE IRRIT. & OTHER ALLERGIC RESPONSES.

=====  
First Aid Measures  
=====

First Aid:EYE:FLUSH WITH WATER 15 MIN. CONSULT MD. SKIN:WASH SKIN W/SOAP & WATER; REMOVE CONTAMINATED CLOTHING & WASH BEFORE REUSE. INHAL:MOVE TO FRESH AIR. CALL MD. INGEST:CALL MD. PROMPTLY

=====  
Fire Fighting Measures  
=====

Flash Point:>212F,>100C  
Extinguishing Media:FOAM,CO\*2,DRY CHEM.  
Fire Fighting Procedures:USE NIOSH/MSHA APPROVED SCBA & FULL PROTECTIVE EQUIPMENT .  
Unusual Fire/Explosion Hazard:NONE SPECIFIED BY MANUFACTURER.

=====  
Accidental Release Measures  
=====

Spill Release Procedures:SCRAPE UP BULK OF MATERIAL. SOAK UP REMAINDER W/CLOTH OR ABSORBENT PAPER. CLEAN W/NON-F LAMMABLE SOLVENT W/PROPER VENTILATION, MFG REC.

=====  
Handling and Storage  
=====

Handling and Storage Precautions:PRACTICE GOOD HOUSEKEEPING & PERSONAL CLEANLINESS TO AVOID SKIN & EYE CONTACT.  
Other Precautions:AVOID BREATHING VAPORS OF HEATED MATERIAL

=====  
Exposure Controls/Personal Protection  
=====

Respiratory Protection:ORGANIC CARTRIDGE RESPIRATOR IF REQUIRED, NIOSH/MSHA APPROVED  
Ventilation:LOCAL EXHAUST RECOMMENDED  
Prote

ctive Gloves:RUBBER

Eye Protection:SAFETY GOGGLES

Other Protective Equipment:COVERALLS, APRON & SKIN BARRIER CREAMS

Supplemental Safety and Health

PART A OF 2 PARTS.KEY1:N1.

===== Physical/Chemical Properties =====

HCC:N1

Boiling Pt:B.P. Text:>212F,>100C

Vapor Pres: