View NSN Online: https://aerobasegroup.co.il/nsn/6850-00-224-9582

EXXON CO USA -- KUTWELL 30 -- 6850-00-224-9582

Product ID:KUTWELL 30 MSDS Date:09/14/1987

FSC:6850

NIIN:00-224-9582

MSDS Number: BDKMQ
=== Responsible Party ===
Company Name:EXXON CO USA
Address:800 BELL STREET

Box:2180

City:HOUSTON

State:TX

ZIP:77252-2180

Country:US

Info Phone Num:713-656-2443

Emergency Phone Num:713-656-3424

CAGE:29667

=== Contractor Identif

ication ===

Company Name: CONVOY OIL CORP Address: 1410 N FRONT STREET

Box:29366

City:PHILADELPHIA

State:PA ZIP:19125 Country:US

Phone:215-739-5281

CAGE:6A438

Company Name: EXXON CO USA

Address:800 BELL ST

Box:2180

City:HOUSTON

State:TX

ZIP:77252-2180

Country:US

Phone:713-656-6449

CAGE:29667

Company Name: EXXON COMPANY U.S.A.

Address:Box:2180 City:HOUSTON

State:TX

ZIP:77252-2180

Country:US

Phone:713-656-5949 / 713-656-3424

CAGE:29700

====== Composition/Information on Ingredients =======

Ingred Name:HYDROTREATED HEAVY NAPHTHENIC DISTILLATE, PETROLEUM CAS:64742-52-5 RTECS #:PY8035000 Fraction by Wt: >85%
Other REC Limits:5 MG/M3 OIL MIST
Ingred Name:PROPRIETARY ADDITIVES Fraction by Wt: >15% Other REC Limits:NONE SPECIFIED
======================================
Effects of Overexposure:PROLONGED OR REPEATED SKIN CONTACT MAY CAUSE MILD SKIN IRRITATION.
======================================
First Aid:IN CASE OF SKIN CONTACT,WASH THOROUGHLY WITH SOAP& WARM WATER.IF SPLASHED INTO THE EYES,FLUSH W/CLEAR WTR FOR 15 MIN OR UNTIL IRRITATION SUBSIDES.
======================================
Flash Point Method:COC Flash Point:315F,157C Lower Limits:0.9% Upper Limits:7% Extinguishing Media:USE WATER FOG, CARBON DIOXIDE, FOAM, OR DRY
CHEMICAL. Fire Fighting Procedures:WEAR FIRE FIGHTING PROTECTIVE EQUIPMENT AND A FULL FACED SELF CONTAINED BREATHING APPARATUS. COO L FIRE EXPOSED
CONTAINERS WITH WATER SPRAY. CONTAIN RUNOFF. Unusual Fire/Explosion Hazard:COMBUSTION OR HEAT OF FIRE MAY PRODUCE HAZARDOUS DECOMPOSITION PRODUCTS AND VAPORS.
========== Accidental Release Measures ============
Spill Release Procedures:RECOVR FREE LIQ.ADD ABS.TO SPILL AREA.KEEP PETROL.PRDCTS OUT OF SEWERS BY DIKING.ADVISE AUTHORITIESIF WTR HAS ENTERED OR MAY ENTER SEWERS OR LAND AREAS.
======================================

=====

Handling and Storage Precautions: KEEP CNTNRS CLSD.DO NOT HANDL/STR.
NEAR HT,FLAME,STRG.OXID.DO NOT CONTAMINATE FLUID.PROVD.BAFFLES ON MACHINS TO MINIMZ OIL MIST.

Other Precautions:AVOID BRTHNG OIL MIST.REMOV.OIL SOAKD CLTHNG, AND LAUNDR BEFOR REUSE.DISCRD OIL-SOAKD SHOES. WASH SKIN THOROUGHLY W/SOAP & WATER AFTER HANDLING.

====== Exposure Controls/Personal Protection ========

Respiratory Protection: NORMLY NOT NEEDED. USE SUPPLIED AIR RESP. PROTECTN IN E

NCLSD SPACES.

Ventilation:USE LOCL EXHAUST.PRVD.GRTR.THAN 60 FPM HOOD FOR ENCLSD SPCS

Protective Gloves: CHEM. RESIST. GLV

Eye Protection: SPLSH GOGGLS OR FACE SHLD

Other Protective Equipment: CHEM.RESIST.APRON.

Supplemental Safety and Health

MSDS DATED 4-16-79./IBP:525F;FBP:885F.

========= Physical/Chemical Properties ===========

HCC:N1
Boiling Pt:B.P. Text:520F,271C
Melt/Freeze Pt:M.P/F.P Text:-10F,-23C
Vapor Pres:5
Spec Gravity:0.9
pH:9.7
Evaporation Rate & Evaporation Ra