View NSN Online: https://aerobasegroup.com/nsn/9150-00-250-0928 VINELAND WAX SPECIALITIES -- PETROLATUM VV-P-236A -- 9150-00-250-0928 Product ID:PETROLATUM VV-P-236A MSDS Date:01/01/1987 FSC:9150 NIIN:00-250-0928 MSDS Number: BDNSW === Responsible Party === Company Name: VINELAND WAX SPECIALITIES Emergency Phone Num:609-697-3152 CAGE:63400 === Contractor Identification === Company Name: VINELAND WAX SPECIALTIES INC WAX PROCESS ING Address: S RAILROAD BLVD Box:City:MINOTOLA State:NJ ZIP:08341 Country:US Phone:609-697-3941 (OUT OF BUSINESS) CAGE:63400 ====== Composition/Information on Ingredients ======== Ingred Name:PETROLATUM Fraction by Wt: 100% ACGIH TLV:2 MG/CUM-FUMES-========== Hazards Identification ================ Effects of Overexposure: INHAL: DIZZ, HEAD RESP TRACT IRRIT. First Aid:HOT WAX BURN:QUENCH IMMED W/COLD TAP WATER. DRY BURN AREA & LOOSELY COVER TO PROTECT AGAINST INFECTION. INHAL:RMV TO FRESH AIR. Flash Point:410F,210C(COC) Extinguishing Media:CO*2,WATER SPRAY OR FOG, DRY CHEMICAL Fire Fighting Procedures: WEAR SCBA & PROTECT CLTHNG. COOL EXPOSED CONTAINERS W/WATER. Unusual Fire/Explosion Hazard: OVER HEATING OF CAN MAY CAUSE HAZARDOUS PRESSURE BUILD-UP ===== Accidental Release Measures =====

==========
Spill Release Procedures:RMV IGNIT SOURCES. ADD ABSORBENT TO SPILL AREA. KEEP OUT OF STORM SEWERS
=========== Handling and Storage ============
Handling and Storage Precautions:KEEP CONTAINERS CLOSED WHEN NOT IN USE. DO NOT HANDLE OR STORE NEAR HEAT OF FLAME. Other Precautions:WASH SKIN THOROUGHLY WITH SOAP & WARM WATER AFTER HANDLING.
====== Exposure Controls/Personal Protection ========
Respiratory Protection:NIOSH/MSHA APPROVE D RESP FOR MIST Ventilation:FACE VELOCITY GREATER THAN 60CFM Protective Gloves:CHEM RESISTANT Eye Protection:SAFETY GLASSES Other Protective Equipment:CHEM RESISTANT APRON Supplemental Safety and Health MSDS DATED 14 JAN, 1987
========= Physical/Chemical Properties ==========
HCC:V6 Boiling Pt:B.P. Text:>550F,288C Vapor Pres:1 Spec Gravity:0.9 Solubility in Water:NEGLIGIBLE Appearance and Odor:BROWN LIGHT GREASE. LIGHT PETROLEUM ODOR.
======== Stability and Reacti
vity Data ==========
Stability Indicator/Materials to Avoid:YES STRONG OXIDANTS Stability Condition to Avoid:EXTREME HEAT Hazardous Decomposition Products:INCOMPLETE COMBUSTION PRODUCES FUMES 8 SMOKE
======= Disposal Considerations ==========
Wests Disposal Methods: DISPOSE I/A AM ALL LOCAL STATE & FEDERAL

Waste Disposal Methods:DISPOSE I/A/W ALL LOCAL, STATE, & FEDERAL

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Dep

REGULATIONS.

artment

of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.