View NSN Online: https://aerobasegroup.com/nsn/7930-00-489-5606

Product ID:WAX-SEAL MSDS Date:01/01/1985 FSC:7930 NIIN:00-489-5606 **MSDS Number: BFBGH** === Responsible Party === Company Name: KARSCAL CORPORATION Emergency Phone Num:213-877-0168 CAGE:LO454 === Contractor Identification === Company Name: KARSCAL CORPORATION CAGE:LO454 Company Name: KARSEAL CORP Address:11552 HART Box:City:NORTH HOLLYWOOD State:CA ZIP:91605-6228 Country:US Phone:818-765-9852 CAGE:05164

Ingred Name:KEROSENE CAS:8008-20-6 RTECS #:OA5500000 Fraction by Wt: 16.8% ACGIH TLV:275

Ingred Name:ALIPHATIC NAPHTHA Fraction by Wt: 54.9% ACGIH TLV:25

Effects of Overexposure:ACUTE:INHALE-ANETH.IRRITATES RESP TRACT.HARMFUL OR FATAL IF SWALLOWED

First Aid:SKIN CONTACT-FLUSH WITH WATER. FOR EYES-FLUSH WATER-15 MINS AND GET MED.ATTN. AFTER HIGH EXPO-GET AIR,RESTORE BREATHING. IF SWALLOWED,CALL DOCTOR IMMEDIATELY. DO NOT INDUCE VOMITTING.

Flash Point:63C Lower Limits:1.3 Upper Limits:NA Extinguishing Media:CO2,DRY CHEMICAL FOAM Fire Fighting Procedures:WATER SPRAY INEFFECTIVE,BUT CAN PROTECT FIREFIGHTER
S & COOL Unusual Fire/Explosion Hazard:COMBUSTIBLE! KEEP CONTAINER TIGHTLY CLOSED. ISOLATE FROM OXIDIZERS,HEAT AND OPEN FLAME.
======================================
Spill Release Procedures: ISOLATE FROM OXIDIZERS, HEAT AND OPEN FLAME.
======================================
Handling and Storage Precautions:STORE IN A COOL AREA.KEEP AWAY FROM HEAT,SPARKS AND OPEN FLAME.EMPTY CONTAINERS HAZARDOUS! CONTINUE ALL LABEL PRECAUTIO NS.
======================================
Respiratory Protection:TLV USE SELF-CONT.AIR PACK.VENT TO KEEP SOLVCONE IN AIR BELOW 25PPM Ventilation:LOC EX-PREF. MECH EX-ACCEPTABLE SOLVENTS Protective Gloves:RECOMMENDED Eye Protection:REQUIRED Other Protective Equipment:NONE Supplemental Safety and Health
SECTION IV-CLOSED CONTAINERS. USE FOG NOZZLES IF WATER IS USED. USE AIR SUPPLIED BREATHING MASKS.PROT CLOTH.

======== Physical/Chemical Propertie

HCC:N1 Boiling Pt:B.P. Text:380-390F Vapor Pres:NA Vapor Density:NA Spec Gravity:1.79 Evaporation Rate & amp; Reference:NONE Solubility in Water:NEG Appearance and Odor:HARD WAXY SOLID. HYDROCARBON ODOR Percent Volatiles by Volume:0.05

Stability Indicator/Materials to Avoid:YES ISOLATE FROM STRONG OXIDIZERS SUCH AS PERMANGANATE Stability Condition to Avoid:ISOLATE FROM HEAT AND OPEN FLAME Hazardous Decomp osition Products:CARB DIOXIDE(FROM BURNING),CARBON MONOXIDE

Waste Disposal Methods:BURY IN LANDFILL AWAY FROM RIVERS AND STREAMS. OBSERVE LOCAL,STATE,FEDERAL HEALTH,SAFETY AND POLLUTION LAWS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or impli ed, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this

document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.