View NSN Online: https://aerobasegroup.co.il/nsn/5960-00-688-6706

MPD INC. -- 7077 ELECTRON-VACUUM TUBE -- 5960-00-688-6706

============= Product Identification ==============

Product ID:7077 ELECTRON-VACUUM TUBE

MSDS Date:08/15/1990

FSC:5960

NIIN:00-688-6706

MSDS Number: BFLTY

=== Responsible Party ===

Company Name: MPD INC.

Address:316 E 9TH ST

City:OWENSBORO

State:KY

ZIP:42301-2312

Country:US

Info Phone Num:502-685-6200

Emergency Phone Num:502-685-6200

CAGE:LO825

=== Contra

ctor Identification ===

Company Name: MPD INC.

Address:316 E 9TH ST

Box:City:OWENSBORO

State:KY

ZIP:42301-2312

Country:US

Phone:502-685-6200

CAGE:LO825

Company Name: MPD INC. (FORMERLY GENERAL ELECTRIC CO)

Address:316 E 9TH STREET

City:OWENSBORO

State:KY

ZIP:42303-2312

Country:US

Phone:502-685-6200

CAGE:33173

====== Composition/Information on Ingredients ========

Ingred Name:RHENIUM 187

Fraction by Wt: 1.89%

Other REC Limits: NONE SPECIFIED

Ingred Name:RHENIUM 187 EMITS 0.008 MEV BE

MICROCURIES/GRAM. RTECS #:9999999ZZ Other REC Limits:NONE SPECIFIED
======================================
Routes of Entry: Inhalation:NO Skin:NO Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:ELECTRON VACUUM TUBES OPERATE AT HIGH TEMPERATURES THAT MAY CAUSE MINOR HEAT RELATED BURNS TO SKIN IF CONTACT IS MADE. Effects of Overex posure:MINOR HEAT RELATED BURNS.
Medical Cond Aggravated by Exposure: NONE SPECIFIED BY MANUFACTURER.
======================================
First Aid:NO EMERGENCY CARE ANTICIPATED.
======================================
Extinguishing Media:NON-FLAMMABLE. USE EXTINGUISHING MEDIA APPROPIATE FOR SURROUNDING FIRE. Fire Fighting Procedures:NONE SPECIFIED BY MANUFACTURER. Unusual Fire/Explosion Hazard:ELECTRON VACUUM TUBES OPERATE UND ER HIGH VACUUM AND IMPLOSION COULD OCCUR AT HIGH TEMPERATURE.
======================================
Spill Release Procedures:HANDLE BROKEN TUBES WITH GLOVES AND FORCEPS. WEAR PROTECTIVE CLOTHING.
============ Handling and Storage ==============
Handling and Storage Precautions: NONE SPECIFIED BY MANUFACTURER. Other Precautions: NONE SPECIFIED BY MANUFACTURER.
====== Exposure Controls/Personal Protection ========
Respirato

TUNGSTEN-RHENIUM ALLOY HAS SPECIFIC ACTIVITY OF 0.00008

TA PARTICLES.

ry Protection:NONE SPECIFIED BY MANUFACTURER. ISE GAS MASK. Protective Gloves:COTTON Eye Protection:SAFETY GLASSES Other Protective Equipment:NONE SPECIFIED BY MANUFACTURER. Work Hygienic Practices:NONE SPECIFIED BY MANUFACTURER. Supplemental Safety and Health TUBE CONTAINS RADIOACTIVE RHENIUM-187. MAXIMUM POSSIBLE ACTIVITY PER ARTICLE IS 0.00000046 MICROCURIE. THESE ARTICLES ARE EXCEPTED FROM RADIOACTIVE LABELING AND NOTIFICATION REQUIREMENTS PER DAC #88-1 4, 252, 223-7005, MIL-STD- 129, ICC ATA-111.1, 173.422, AND MIL-HBDK-6000.
========= Physical/Chemical Properties =========
HCC:A2 Appearance and Odor:WHITE CERAMIC AND GOLD METAL. NO ODOR.
============= Stability and Reactivity Data ===========
Stability Indicator/Materials to Avoid:YES NONE Hazardous Decomposition Products:NONE
======= Disposal Considerations ==========
Waste Disposal Methods:BROKEN OR SPENT TUBES SHOULD BE DISPOSED OF AS SPECIFIED I N PARAGRAPH 20.301,10CFR PART 20,CODE OF FEDERAL REGULATIONS.IF PROPER DISPOSAL PRESENTS A PROBLEM,RETURN TO MANUFACTURER.COMPLY WITH APPLICAB LE FEDERAL,STATE AND LOCAL ENVIRONMNTL REGULATIONS
Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their

particular situation.