View NSN Online: https://aerobasegroup.com/nsn/3439-01-012-1003

MUREX WELDING PRODUCTS -- MUREX MGAW TYPE A675 -- 3439-01-012-1003

Product ID:MUREX MGAW TYPE A675 MSDS Date:01/01/1987 FSC:3439 NIIN:01-012-1003 MSDS Number: BGDGP === Responsible Party === Company Name: MUREX WELDING PRODUCTS Emergency Phone Num: (201)464-5830 CAGE:7A276 === Contractor Identification === Company Name: MUREX WELDING PRODUCTS Address:575 MOUNTAIN A VE Box:922 City:NEW PROVIDENCE State:NJ ZIP:07974-2006 Country:US CAGE:7A276

Ingred Name:IRON OXIDE CAS:1309-37-1 RTECS #:NO7400000 Fraction by Wt: 98%. OSHA PEL:10 MG/M3 (FE) ACGIH TLV:5 MG/M3(FE),B2; 9293

Ingred Name:MANGANESE (SARA III) CAS:7439-96-5 RTECS #:OO9275000 Fraction by Wt: 1.4% OSHA PEL:(C) 5 MG/M3 DUST ACGIH TLV:5 MG/M3 DUST 9293

Ingred Name:SILICON CAS:7440-21-3 RTECS #:VW0400000 OSHA PEL:15 MG/M3 TDUST ACG

IH TLV:10 MG/M3 TDUST; 9293
======================================
Effects of Overexposure:DIZZ;NAUSEA;IRR.OF NOSE,THROAT,EYES.
======================================
First Aid:REMOVE TO FRESH AIR.OBTAIN MED.ATTN.
======================================
Extinguishing Media:EXTINGUISH WITH AGENT SUITABLE FOR SURROUNDING FIRE Unusual Fire/Explosion Hazard:WELDING ARC AND SPARKS CAN IGNITE COMBUSTIBLE PRODUCTS.
======================================
Spill Release Procedures: CLEAN UP ANY GRINDING DUST OR WASTE RESIDUE AND PLACE IN SUITABLE DOT APPVD DISPOSAL CONTAINER.
======================================
Other Precautions:TRAIN WELDER TO KEEP HIS HEAD OUT OF THE FUMES.MONITOR AIR TO ENSURE ACCEPTABLE EXPOSURES.AVOID ELECTRICAL SHOCK BY MAINTAINING DRY WORK AREA.
======================================
Respiratory Protection:FUME RESP.OR AIR SUPPLIED RESP.IN CONFINED SPACES. Ventilation:LOCAL EXHAUST TO MAINTN BELOW TLV. Protective Gloves:WELDER'S GLOVES Eye Protection:FACE SHLD W/FILTER LENS. Other Protective Equipment:SUBST.DK.CLOTH,ARM PROTECTOR,APRON,HAT,SHOULDR.PROTECTION. Supplemental Safety and Health MSDS DATED 03-08-82/HAZ.DECOMP.PROD:CO,NO*2&O*3

HCC:N1 Appearance and Odor:0.045 IN DIA WELDIN G ROD IN A SPOOL.

Stability Indicator/Materials to Avoid:YES NONE Stability Condition to Avoid:NONE Hazardous Decomposition Products:FUMES OF METALS&METAL OXIDE INCLUD.BASE METL&COATING-SEE SUP

Waste Disposal Methods: DISPOSE OF IAW LOCAL, STATE, FED. REGS.

Disclaimer (provided with this information by the compiling agencies): This information is formulat

ed for use by elements of the Department

of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.