View NSN Online: https://aerobasegroup.co.il/nsn/6830-00-261-7445

TEXACO INC -- 60001 PROPANE -- 6830-00-261-7445

Product ID:60001 PROPANE MSDS Date:06/28/1988 FSC:6830 NIIN:00-261-7445 MSDS Number: BJKXB === Responsible Party === **Company Name: TEXACO INC** Box:509 **City:BEACON** State:NY ZIP:12508-0509 Country:US Info Phone Num:914-831-3400 EXT 204 Emergency Phone Num:409-722-8381 OR 800-424-9300 CHEMT Preparer's Name: F. E. BENTL EΥ CAGE:7B131 === Contractor Identification === Company Name: TEXACO INC Box:509 **City:BEACON** State:NY ZIP:12508-0509 Country:US Phone:914-831-3400 CAGE:7B131 Ingred Name: PROPANE CAS:74-98-6 RTECS #:TX2275000 Fraction by Wt: 100% Other REC Limits:NONE SPECIFIED OSHA PEL:1000 PPM ACGIH TLV:ASPHYXIANT; 9192

Routes of Entry: Inhalation:YES Skin:YES Ingestion:

YES

Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO

Health Hazards Acute and Chronic:ACUTE: OVEREXPOSURE MAY LEAD TO CENTRAL NERVOUS SYSTEM DEPRESSION, LEADING TO IRRITATION, HEADACHE, NAUSEA, DIZZINESS, FATIGUE, CONFUSION AND UNCONSCIOUSNESS. EYES/SKIN: IRRITATION - LIQUID CAUSES FRO STBITE BURNS. INGESTION: MAY LEAD TO VOMITING. CHRONIC: NONE KNOWN. GAS CAN ACT AS AN ASPHYXIANT.

Explanation of Carcinogenicity: THE COMPONENTS OF THIS PRODUCT HAVE NOT SHOWN ANY EVIDE

NCE OF BEING CARCINOGENIC.

Effects of Overexposure:OVEREXPOSURE MAY LEAD TO RESPIRATORY IRRITATION, NAUSEA, FATIGUE, DIZZINESS, HEADACHES, UNCONSCIOUSNESS, AND EYE IRRITATION. LIQUID CAN ACT AS A CRYOGENIC AND CAUSE FROSTBITE BURNS.

Medical Cond Aggravated by Exposure: PERSONS WITH A SKIN DISORDER SHOULD USE CAUTION WHEN HANDLING OR USING THIS PRODUCT.

First Aid:SKIN: REMOVE CONTAMINATED CLOTHING. WASH WITH SOA P AND WATER.

GET MEDICAL ATTENTION IF IRRITATION PERSISTS. INHALATION: REMOVE TO FRESH AIR & RESTORE BREATHING IF NECESSARY. GET MEDICAL ATTENTION. EYE : IMMEDIATELY FLUSH WITH WATER FOR 15 MINUTES WHILE HOLDING EYELIDS OPEN. GET MEDICAL ATTENTION. INGESTION: GET IMMEDIATE MEDICAL ATTENTION. DO NOT INDUCE VOMITING. NOTHING BY MOUTH IF UNCONSCIOUS.

Flash Point:-156F,-104C
Lower Limits: 2.37
Upper Limits:
9.5
Extinguishing Media:STOP FLOW OF GAS AND USE WATER TO COOL
CONTAINERS.ALLOW FIRE TO BURN OUT.USE CARBON DIOXIDE/ DRY CHEMICAL
FOR SMALL FIRE
Fire Fighting Procedures:FIRE FIGHTERS SHOULD USE NIOSH APPROVED SCBA &
FULL PROTECTIVE EQUIPMENT WHEN FIGHTING CHEMICAL FIRE. USE WATER
SPRAY TO COOL NEARBY CONTAINERS EXPOSED TO FIRE.
Unusual Fire/Explosion Hazard:FIRE OR EXCESSIVE HEAT MAY CAUSE
PRODUCTION OF HAZARDOUS DECOMPOSITION PRODUCTS. EXPLOSIVE AIR-VAPOR
MIXTURES CAN E

ASILY FORM.

Spill Release Procedures: SHUT DOWN TRANSFER OPERATION AND STOP LEAK IF POSSIBLE. ELIMINATE SOURCES OF IGNITION. KEEP AWAY UPWIND AND WARN PEOPLE DOWNWIND OF POSSIBLE EXPLOSION. WEAR SCBA.

Handling and Storage Precautions:STORE IN A COOL, VENTILATED WORK AREA. KEEP CONTAINERS CLOSED WHEN NOT IN USE. COMBUSTIBLE LIQUID; EMPTY CONTAI

NERS CAN BE HAZARDOUS.

Other Precautions: THE SELECTION OF PERSONAL PROTECTIVE EQUIPMENT SHOULD BE MADE BY THE MATERIAL USER BASED ON THE PARTICULAR CONDITIONS WHERE THE MATERIAL IS TO BE USED TOGETHER WITH INFORMATION CONTAINED IN THIS MSDS.

Respiratory Protection: USE NIOSH/MSHA APPROVED RESPIRATOR. AIR-SUPPLIED OR FILTERING TYPE WITH ORGANIC VAPOR CARTRIDGES ARE RECOMMENDED. Ventilation:LOCAL AND MECHANICAL EX HAUST RECOMMENDED. AVOID OPEN ELECTRICAL SOURCES NEAR PRODUCT VAPOR AREAS. Protective Gloves: USE INSULATED WORK GLOVES Eye Protection: USE CHEMICAL SAFETY GOGGLES & FACESHIELD Other Protective Equipment: EYE WASH STATION & SAFETY SHOWER. Work Hygienic Practices: DO NOT TAKE INTERNALLY. AVOID SKIN CONTACT. WASH SKIN AFTER USING PRODUCT. DO NOT EAT, DRINK OR SMOKE IN WORK AREA. Supplemental Safety and Health LIQUID AND LIQUID COOLED EQUIPMENT CAN CAUSE FROSTBITE BURNS. VAPOR **REDUCES A** VAILABLE OXYGEN FOR BREATHING. USE ONLY IN WELL VENTILLATED AREA.

HCC:G2 Boiling Pt:B.P. Text:-40F,-40C Vapor Pres:10 @27 Vapor Density:1.55 AIR=1 Spec Gravity:0.5077 Solubility in Water:APPRECIABLE Appearance and Odor:ODORLESS,COLORLESS GAS

Stability Indicator/Materials to Avoid:YES STRONG OXIDIZING AGENTS Stability Condition to Avoid:HIGH TEMPERATURES

, SPARKS, AND OPEN FLAMES Hazardous Decomposition Products:CARBON MONOXIDE, CARBON DIOXIDE AND OTHER HYDROCARBONS COMPOUNDS DURING COMBUSTION.

Waste Disposal Methods:DISPOSAL OF RAW MATERIAL AND POSSIBLY CLEAN-UP MATERIAL WOULD BE AS A HAZARDOUS WASTE (EPA CODE D001).

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defens

e. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.