

MCGEAN-ROHCO INC, CEE-BEE DIV. -- CEE-BEE STRIPPER A-256 -- 8010-01-023-0343

=====
Product Identification
=====

Product ID:CEE-BEE STRIPPER A-256

MSDS Date:07/01/1990

FSC:8010

NIIN:01-023-0343

MSDS Number: BLLWV

=== Responsible Party ===

Company Name:MCGEAN-ROHCO INC, CEE-BEE DIV.

Address:9520 E CEE BEE DR

City:DOWNEY

State:CA

ZIP:90241

Country:US

Info Phone Num:213-803-4311

Emergency Phone Num:2

13-803-4311/800-424-9300(CHEMTREC)

Preparer's Name:H. B. HANS

CAGE:71361

=== Contractor Identification ===

Company Name:MCGEAN-ROHCO INC

Address:9520 E CEE BEE DR

Box:City:DOWNEY

State:CA

ZIP:90241-5501

Country:US

Phone:562-803-4311/FAX: 562-803-6701

CAGE:71361

=====
Composition/Information on Ingredients
=====

Ingred Name:METHYLENE CHLORIDE (SARA III)

CAS:75-09-2

RTECS #:PA8050000

Fraction by Wt: 45-55%

Other REC Limits:NONE SPECIFIED

OSHA PEL:500 PPM/C,1000; Z2

ACGIH TLV:50

PPM, A2; 9192
EPA Rpt Qty:1000 LBS
DOT Rpt Qty:1000 LBS

Ingred Name:PHENOL (SARA 313)
CAS:108-95-2
RTECS #:SJ3325000
Fraction by Wt: 5-15%
Other REC Limits:NONE SPECIFIED
ACGIH TLV:19 MG/M3
EPA Rpt Qty:1000 LBS
DOT Rpt Qty:1000 LBS

Ingred Name:TOLUENE (SARA III)
CAS:108-88-3
RTECS #:XS5250000
Fraction by Wt: 1%
Other REC Limits:NONE SPECIFIED
OSHA PEL:200 PPM/150 STEL
ACGIH TLV:50 PPM; 9293
EPA Rpt Qty:1000 LBS
DOT Rpt Qty:1000 LBS

Ingred Name:SODIUM CHROMATE (SARA III)
CAS:7775-11-3
RTECS
#:GB2955000
Fraction by Wt: .1-1.0%
Other REC Limits:NONE SPECIFIED
OSHA PEL:0.1 PPM CRO3;CEILING
ACGIH TLV:0.05 MG CR/M3; 9192
EPA Rpt Qty:10 LBS
DOT Rpt Qty:10 LBS

===== Hazards Identification =====

Routes of Entry: Inhalation:YES Skin:YES Ingestion:NO
Reports of Carcinogenicity:NTP:YES IARC:YES OSHA:YES
Health Hazards Acute and Chronic:CORROSIVE TO EYES AND SKIN. READILY
ABSORBED THROUGH THE SKIN. LONG TERM EXPOSURE COULD CAUSE DAMAGE TO
LIV

ER, BLOOD OR KIDNEYS. VAPORS CAN CAUSE DIZZINESS, NAUSEA.
Explanation of Carcinogenicity:METHYLENE CHLORIDE AND SODIUM CHROMATE
ARE SUSPECTED CARCINOGENS.

=====
First Aid Measures
=====

First Aid:WASH SKIN WITH SOAP AND WATER. FLUSH EYES WITH WATER FOR AT
LEAST 15 MINUTES. GET MEDICAL ATTENTION. FOR INHALATION, REMOVE TO
FRESH AIR. IF SYMPTOMS PERSIST, SEEK MEDICAL ATTENTION.

=====
Fire Fighting Measures
=====

Flash Point:NA

Fire Fighting Procedures:IF INVOLVED IN A FIRE, SELF-CONTAINED
BREATHING APPARATUS SHOULD BE WORN.

Unusual Fire/Explosion Hazard:IN DIRECT FLAME, PHOSGENE CAN FORM.

=====
Accidental Release Measures
=====

Spill Release Procedures:ABSORB WITH AN ABSORBENT SUCH AS VERMICULITE.
PLACE IN SUITABLE CONTAINER.

=====
Handling and Storage
=====

Handling and Storage Precautions:STORE IN CLOSED CONTAINERS IN COOL,
DRY, WELL-VENTILATED AREA (32-90 DEGREES F). OPEN CONTAINERS SLOWLY
AND WITH CAUTION.

=====
Exposure Controls/Personal Protection
=====

Respiratory Protection:NIOSH OR MSHA APPROVED ORGANIC CARTRIDGE
RESPIRATOR.

Ventilation:SUFFICIENT TO KEEP BELOW TLV LIMITS.

Protective Gloves:NEOPRENE.

Eye Protection:CHEMICAL GOGGLES AND FACE SHIELD.

Other Protective Equipment:SUFFICIENT TO PREVENT SKIN CONTACT.

Supplemental Safety and Health

=====
Physical/Chemic

al Properties =====

HCC:T4

Boiling Pt:B.P. Text:110F,43C

Vapor Density:2.9

Spec Gravity:1.15

pH:10.0

Evaporation Rate & Reference: