View NSN Online: https://aerobasegroup.co.il/nsn/2530-00-506-9334

ABEX CORP FRICTION PRODUCTS GROUP -- 931-92,NON-ASBESTOS BRAKE LININGS 2530-00-506-9334

Product ID:931-92, NON-ASBESTOS BRAKE LININGS MSDS Date:01/09/1989 FSC:2530 NIIN:00-506-9334 MSDS Number: BPJCW === Responsible Party === Company Name: ABEX CORP FRICTION PRODUCTS GROUP Address:2610 PAPER MILL RD Box:3250 City:WINCHESTER State:VA ZIP:22601-3250 Country:US Info Phone Num:703-662-3871/703-665-2270 Emergency Phone Num:703-662-3842 Preparer's Name:M. K. LEUNG CAGE:85117 === Contractor Identification === Company Name: ABEX CORP FRICTION PRODUCTS GROUP Address:2610 PAPER MILL RD Box:3250 City:WINCHESTER State:VA ZIP:22601-3250 Country:US Phone:703-665-2270 CAGE:85117

Ingred Name:GLASS FIBERS Other REC Limits:NONE RECOMMENDED OSHA PEL:10.0 MG/M3 (MFR) ACGIH TLV:10.0 MG/M3 (MFR)

Ingre

d Name:SILICA, CRYSTALLINE - TRIPOLI CAS:1317-95-9 RTECS #:VV7336000 Other REC Limits:NONE RECOMMENDED OSHA PEL:SEE TABLE Z3 ACGIH TLV:0.1 MG/M3 RDUST;9293

Ingred Name:CARBON BLACK CAS:1333-86-4 RTECS #:FF5800000 Other REC Limits:NONE RECOMMENDED OSHA PEL:3.5 MG/M3 ACGIH TLV:3.5 MG/M3; 9293

Ingred Name:PHENOLIC COMPOUND/PHENOLIC AND ELASTOMER COMPOUNDS Other REC Limits:NONE RECOMMENDED OSHA PEL:19.0 MG/M3 (MFR) ACGIH TLV:19.0 MG/M3 (MFR)

Ingred Name:WOOD FLOUR/WOOD FLOUR AND OTHER FILLERS Oth er REC Limits:NONE RECOMMENDED OSHA PEL:1.0 MG/M3 (MFR) ACGIH TLV:1.0 MG/M3 (MFR)

Ingred Name:IRON,ZINC,ALUMINUM,BRASS AND THEIR OXIDES Other REC Limits:NONE RECOMMENDED OSHA PEL:10 MG/M3 (MFR) ACGIH TLV:10 MG/M3 (MFR)

LD50 LC50 Mixture:TLV FOR SILICA IS 0.1 MG/M3. Routes of Entry: Inhalation:YES Skin:YES Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:YES OSHA:NO Health Hazards Acute and Chronic:ACUTE & CHRONIC-SO ME PERSONS MAY BE

SENSITIVE TO CASHEW RESINS & DEVELOP DERMATITIS-TYPE PROBLEMS.DUST OF GLASS,SILICA,TALC,GRAPHITE,CARBON BLACK & COAL CAN PRODUCE PNEUMOCONIOSIS & OTHER LUNG DAMAGE. METAL DUSTS CAN BE IRRITANTS OF THE EYES & UPPER RESPIRATORY SYSTEM.THERE IS LITTLE EVIDENCE OF HARM BY FE,AL,ZN DUSTS.

Explanation of Carcinogenicity:THE INTERNATIONAL AGENCY FOR RESEARCH ON CANCER (IARC) HAS CLASSIFIED CERAMIC FIBERS,MINERAL WOOL AS POSSIBLE CARCINOGEN Effects of Overex posure:CASHEW RESINS-SKIN ERUPTIONS SIMILAR TO POISON IVY. PNEUMOCONIOSIS-COUGHING, WHEEZING, SHORTNESS OF BREATH, IMPAIRED PULMONARY FUNCTION.DUSTS IN EYE MAY CAUSE IRRITATION.GASTROINTESTINAL DISTURBANCES POS SIBLE FROM INGESTION.GLASS FIBER MAY CREATE TRANSIENT MECHANICAL IRRITATION OF THE SKIN OF SOME PERSONS.
Medical Cond Aggravated by Exposure:PERSONS WITH PRE-EXISTING SKIN DISORDERS OR EYE PROBLEMS OR IMPAIRED RESPIRATORY FUNCTION MAY BE MORE SUSCEPTIBLE TO THE EF

FECTS OF THE SUBSTANCE.

First Aid:GET MEDICAL ATTENTION IF NEEDED. SKIN:WASH WITH SOAP & WATER. EYE:FLUSH WITH WATER FOR 15 MINUTES, HOLDING EYELIDS OPEN. INHALED:REMOVE TO FRESH AIR. ORAL:CALL A PHYSICIAN.

Flash Point:NONE
Extinguishing Media:WATER (CLASS A, B, OR C)
Fire Fighting Procedures:WEAR FULL PROTECTIVE CLOTHING AND NIOSH-APPROVED SEL
F-CONTAINED BREATHING APPARATUS WITH FULL
FACEPIECE OPERATED IN THE POSITIVE PRESSURE MODE.
Unusual Fire/Explosion Hazard:NONE KNOWN

Spill Release Procedures: GRINDING, DRILLING, MILLING ETC. CAN RESULT IN THE RELEASE OF AIRBORNE DUST. WEAR PROTECTIVE CLOTHING AND NIOSH-APPROVED DUST RESPIRATOR. VACUUM OR WET SWEEP TO REMOVE SPILLS. TRANSFER TO APPROPRIATE CONTAINERS FOR DISPOSAL. DO NOT RAISE DUST.

Handling and Storage Precautions: STORAGE- STORE IN COOL PLACE. AVOID GENERATING DUSTS.

Other Precautions: PRE-EMPLOYMENT SCREENING FOR ALLERGIES AND HISTORIES OF SKIN SENSITIVITIES MAY BE BENEFICIAL IN DETERMINING PERSONS SENSITIVE TO CASHEW MATERIALS.

======= Exposure Controls/Personal Protection ==========

Respiratory Protection:NIOSH-APPROVED FOR PNEUMOCONIOSIS-FIBROSIS PRODUCING DUSTS AND DUSTS WIT H TLV NOT LESS THAN 0.05 MG/M3. Ventilation: LOCAL EXHAUST FOR DUST EXPOSURES EXCEEDING TLV. Protective Gloves: RECOMMENDED Eye Protection: RECOMMENDED FOR DUSTY CONDITIONS Other Protective Equipment: LONG SLEEVE SHIRTS OR OTHER PROTECTIVE CLOTHING, EYE BATH FOUNTAIN, QUICK EMERGENCY SHOWER. Work Hygienic Practices: EMPLOYEES SHOULD BE PROPERLY INSTRUCTED IN THE USE OF CONTROL MEASURES AS INDICATED ABOVE WHEN THERE IS A NEED FOR IT. Supplemental Safety and Health AVOID SCRAPING OR SCRATCH ING BRAKE LININGS OR OTHERWISE CREATING DUST DURING ASSEMBLY. USE LOCAL EXHAUST VENTILATION AT ALL TIMES. COMPRESSED AIR SHOULD NOT BE USED FOR CLEANING UP DUST FROM LININGS. USE HEPA FILTERED VACUUM. USE BARRIER CREAMS FOR PERSONS WITH SKIN SENSITIVE TO CASHEW RESINS AND FIBER GLASS. HCC:N1 Spec Gravity:1.5 - 3.5 Solubility in Water:NO Appearance and Odor:SOLID, DARK GREY COLOR, FRICTION MATERIAL ODOR ===== Stability Indicator/Materials to Avoid:YES Stability Condition to Avoid:NONE KNOWN Hazardous Decomposition Products: CARBON MONOXIDE AND CARBON DIOXIDE Waste Disposal Methods: DISPOSE OF IN ACCORDANCE WITH ALL LOCAL, STATE AND FEDERAL REGULATIONS. Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their

particular situation.