View NSN Online: https://aerobasegroup.co.il/nsn/2530-01-127-4082

FERODO AMERICA -- MG-18 BRAKE LINING-CURED -- 2530-01-127-4082

Product ID:MG-18 BRAKE LINING-CURED MSDS Date:07/19/1991 FSC:2530 NIIN:01-127-4082 **MSDS Number: BPQXD** === Responsible Party === Company Name: FERODO AMERICA Address:1 GRIZZLY LN City:SMITHVILLE State:TN ZIP:37166 Country:US Info Phone Num:800-626-5093 Emergency Phone Num:800-626-5093/800-424-9300(CH EMTREC) CAGE:FEROD === Contractor Identification === Company Name: FERODO AMERICA Address:1375 HEIL QUAKER BOULEVARD Box:7010 City:LAVERGNE State:TN ZIP:37086-7010 Country:US Phone:800-646-5093 CAGE:FEROD Company Name: FERODO AMERICA - PREVIOUSLY NUTURN CORP. Address:1 GRIZZLY LN Box:City:SMITHVILLE State:TN ZIP:37166 Country:US Phone:800-626-5093/800-424-9300(CHEMTREC) CAGE:0V0F1

Ingred Name:ASBESTOS (FRIABLE) (SARA III) CAS:1

332-21-4 RTECS #:CI6425000 Fraction by Wt: > 50% Other REC Limits:NONE RECOMMENDED OSHA PEL:SEE 1910.1001 ACGIH TLV:0.2 - 2 FIBERS/CC EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

Ingred Name:TALC (CONTAINING ASBESTOS) CAS:14807-96-6 RTECS #:MW2700000 Fraction by Wt: < 5% Other REC Limits:NONE RECOMMENDED OSHA PEL:0.2 FIBERS/CC ACGIH TLV:0.2 FIBERS/CC; 9293

Ingred Name:COAL DUST Fraction by Wt: < 10% Other REC Limits:NONE RECOMMENDED OSHA PEL:0.1 MG/CM RDUST(MFR) ACGIH TLV:0.1 MG/CM RDUST(MFR)

=========

LD50 LC50 Mixture:TLV FOR ASBESTOS FIBER IS 0.2 FIBERS/CC. Routes of Entry: Inhalation:YES Skin:YES Ingestion:NO Reports of Carcinogenicity:NTP:YES IARC:YES OSHA:YES Health Hazards Acute and Chronic:ACUTE-NONE UNDER NORMAL CONDITIONS OF USE.GRINDING,SANDING OR MACHINING MAY PRODUCE DUST THAT CAN CAUSE IRRITATION OF EYES,SKIN & RESPIRATORY PASSAGES.CHRONIC-LONG TERM EXPOSURE TO ASBESTOS CAN CAUSE IRREVERSIBLE ASBESTOS IS,LUNG DISEASE,LUNG CANCER.INGESTION OF DUST MAY CAUSE GI IRRITATION. SKIN CONTACT CAUSES RASH. Explanation of Carcinogenicity:ASBESTOS IS REGULATED BY OSHA AS A CARCINOGEN.

Effects of Overexposure:NONE UNDER NORMAL CONDITIONS OF USE. GRINDING, SANDING OR MACHINING MAY PRODUCE DUST THAT CAN CAUSE IRRITATION OF EYES, SKIN & RESPIRATORY PASSAGES. LONG TERM EXPOSURE TO ASBESTOS CAN CAUSE IRREVERSIB LE ASBESTOSIS, LUNG DISEASE, LUNG CANCER. INGESTION OF DUST MAY CAUSE GI

IRRITATION. SKIN CONTACT CAUSES RASH.
Medical Cond Aggravated by Exposure:PERSONS WITH PRE-EXISTING SKIN DISORDERS SUCH AS DERMATITIS, LUNG DISEASE OR ANY CONDITION THAT MAY BE AGGRAVATED BY NUISANCE DUST OR FIBERS.
======================================
First Aid:SHOULD NOT BE NECESSARY FROM A PROPER HANDLING. HOWEVER, SEEK MEDICAL ATTENTION IF SYMPTOMS DEVELOP. IN CASE OF EYE IRRITATION GENTLY RINSE WITH WATER FOR 15 MINUTES WHILE KEEPING EY ELIDS OPEN.
SKIN: WASH FREQUENTLY WITH SOAP AND WATER. INHALATION: REMOVE TO FRESH AIR. INGESTION: CALL PHYSICIAN.
======================================
Flash Point:NON FLAMMABLE Extinguishing Media:WATER SPRAY, CARBON DIOXIDE, FOAM OR DRY CHEMICAL FOR SURROUNDING FIRE. USE WATER SPRAY TO COOL FIRE EXPOSED
CONTAINERS. Fire Fighting Procedures:WEAR FULL PROTECTIVE CLOTHING AND NIOSH-APPROVED SELF-CONTAINED BREATHING APPARATUS. Unusual Fire/Exp
losion Hazard: ASBESTOS FIBERS MAY BE RELEASED IN A FIRE. THIS PRODUCT IS INHERENTLY FLAME RESISTANT BUT MAY IGNITE AT TEMPERATURES ABOVE 1112F(600C)IN AN OXYGEN ENRICHED AIR.
======================================
Spill Release Procedures: TREAT DUST AS FREE ASBESTOS. DO NOT DRY SWEEP OR USE COMPRESSED AIR. WET METHOD SHOULD BE USED FOR EXTRACTION OF DUST AND DEBRIS. HIGH EFFICIENCY PARTICULATE APPARATUS (HEPA) VACUUMS SHOULD BE USED.
Neutralizin g Agent:NOT APPLICABLE.
======================================
Handling and Storage Precautions:STORAGE- AVOID CREATING DUST BY SANDING OR GRINDING THE PRODUCT.

Other Precautions:USE IN WELL VENTILATED AREA. AVOID BREATHING DUST OR FIBERS. MINIMIZE CONTACT WITH SKIN. AVOID CONTACT WITH EYES. DO NOT RAISE DUST. WASH THOROUGHLY AFTER HANDLING AND BEFORE EATING OR DRINKING. KEEP AWAY FROM REACH OF CHILDREN.

====== Exposure Controls/Personal P

rotection =========

Respiratory Protection: USE NIOSH APPROVED HIGH EFFICIENCY FIBERS/FUMES RESPIRATOR WHEN AIRBORNE FIBER CONCENTRATIONS EXCEED THE PEL. Ventilation:LOCAL/GENERAL TO MAINTAIN PEL/TLV. CHECK LOCAL REGULATIONS FOR EMISSION STANDARDS. Protective Gloves: LEATHER, COTTON OR RUBBER AS NEEDED Eye Protection: DUST-RESISTANT SAFETY GOGGLES Other Protective Equipment: EYE WASH STATION AND SAFETY SHOWER, WORK CLOTHING AND APRON AS REQUIRED. DO NOT WEAR CONTACT LENSES Work Hyg ienic Practices: DON'T TAKE PROTECTIVE GEAR/CLOTHING HOME IF EXPOSED TO DUST. DON'T SHAKE. DON'T EAT IN AREA WHERE ASBESTOS/DUST PRESENT. Supplemental Safety and Health THIS PRODUCT IS FULLY CURED IN THE MANUFACTURING PROCESS. HCC:T6 Spec Gravity:1.8 - 1.9 Solubility in Water: INSOLUBLE Appearance and Odor:SOLID - LINSEED OIL ODOR Stability Indicator/ Materials to Avoid:YES NONE Stability Condition to Avoid: STABLE AT NORMAL TEMPERATURES AND STORAGE CONDITIONS. Hazardous Decomposition Products:NONE

Waste Disposal Methods:WASTE SHOULD BE CONTAINED IN IMPERMEABLE BAGS, LABELED AND DISPOSED IN ACCORDANCE WITH ALL LOCAL, STATE AND FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by e

lements of the Department

of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.