View NSN Online: https://aerobasegroup.co.il/nsn/3439-01-325-7641

Product ID:ARCAIR SLICE CUTTING ROD, UNCOATED MSDS Date:07/01/1989 FSC:3439 NIIN:01-325-7641 **MSDS Number: BXWGN** === Responsible Party === **Company Name: TWECO PRODUCTS INC** Address:4200 W HARRY STREET Box:12250 City:WICHITA State:KS ZIP:67277 Country:US Info Phone Num:316-942-1421 Emerge ncy Phone Num:316-942-1421 Preparer's Name: DENNIS WILSON CAGE:89381 === Contractor Identification === Company Name: TWECO PRODUCTS, INC. Address:4200 WEST HARRY ST. Box:12250 City:WICHITA State:KS ZIP:67277 Country:US Phone:316-946-8308;316-942-1421 CAGE:89381

Ingred Name:MILD STEEL Fraction by Wt: 99% Other REC Limits:NONE RECOMMENDED

Routes of Entry: Inha

 lation:NO Skin:NO Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:INHALATION-WHEN CUTTING CERTAIN MATERIALS, AIRBORNE CONCENTRATION MAY EXCEED TLV. VISUAL-EXPOSURE TO ULTRA-VIOLET RADIATION FROM A POWERED ARC CAN RESULT IN KERATONCONJUNCTIVITIS. Explanation of Carcinogenicity:NOT LISTED. Effects of Overexposure:INHALATION-CAUSING DRYNESS OF THE THROAT, BREATHING DIFFICULTY OR UNCONSCIOUSNESS. VISUAL-CAUSING INFLAMMATION, BLU RRED VISION AND HEADACHE. Medical Cond Aggravated by Exposure:POSSIBLY EXISTING RESPIRATORY.
======================================
First Aid:INHALATION-REMOVE TO FRES AIR AND SEEK MEDICAL ATTENTION. VISUAL-CONSULT A PHYSICIAN, PREFERABLY AN EYE SPECIALIST.
======================================
Extinguishing Media:NONE SPECIFIED BY MANUFACTURER. Fire Fighting Procedures:DOES NOT BURN READILY. Unusual Fire/Explosion Hazard:NONE.
======================================
Spill Release Procedures: PICK UP SPENT ENDS WHEN COOL.
======================================
Handling and Storage Precautions:STORE IN A LOW HUMIDITY ENVIRONMENT. Other Precautions:AVOID BREATHING VAPOR! INTENSE HEAT GENERATED WHEN IN OPERATION!
======================================
Respiratory Protection:NIOSH-MESA DETERMINED FOR FUME/DUST PROTECTION. AS REQUIRED TO MAINTAIN BELOW TLV'S. Ventilation:PREFERRED FOR FUME/DUST REDUCTION. Protective Gloves:AS USED IN CONVENTIONAL ARC WELDING. Eye Protection:FACE SHIELD; FILTER LENS FOR U.V. PROTE. Other Protective Equipment:AS USED IN CONVENTIONAL ARC WELDING. FOOTWARE: SUITABLE FOR METAL WORKING. Work Hygienic Practices:OPERATOR TRAINED TO AVOID ELECTRICAL SHOCK AND U.V. RAY EXPOSURE. Supplemental Safety and Health

HCC:N1 Solubility in Water:INSOLUBLE Appearance and Odor:SOLID. ROLLED STEEL TUBE, NO NOTABLE ODOR.

Stability Indicator/Materials to Avoid:YES NONE KNOWN Hazardous Decomposition Products:IRON OXIDE FUMES IN ADDITION TO THESE GENERATED BY MATERIALS BEING CUT.

Waste Disposal Methods: SOLID LANDFILL IF LOCAL REGULATIONS ALLOW.

Disclaimer (provided with th

is information by the compiling agencies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.