

FLAMEMASTER CORP -- CS 2725 PART B -- 8030-00-670-8556

=====  
Product Identification  
=====

Product ID:CS 2725 PART B

MSDS Date:03/24/1993

FSC:8030

NIIN:00-670-8556

Kit Part:Y

MSDS Number: CBTQL

=== Responsible Party ===

Company Name:FLAMEMASTER CORP

Address:11120 SHERMAN WAY

City:SUN VALLEY

State:CA

ZIP:91352

Country:US

Info Phone Num:818-982-1650

Emergency Phone Num:800-424-9300(CHEMTREC)

Prepa

er's Name:HERBERT H. MOORE

CAGE:14439

=== Contractor Identification ===

Company Name:FLAMEMASTER CORP THE CHEM SEAL DIV

Address:11120 SHERMAN WAY

Box:City:SUN VALLEY

State:CA

ZIP:91352-4949

Country:US

Phone:818-982-1650

CAGE:14439

=====  
Composition/Information on Ingredients  
=====

Ingred Name:TRIETHYLENE PENTAMINE

CAS:68822-50-4

RTECS #:TQ0525000

Fraction by Wt: 0.5%

Other REC Limits:5 PPM (SKIN)

Ingred Name:VOC - 1 GM/LITER

Other REC Limits:NONE SPECIFIED

=====

==== Hazards Identification =====

Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES  
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO  
Health Hazards Acute and Chronic:VAPOR/MIST CAN IRRITATE THE NOSE AND THROAT. SEVERELY IRRITATING TO EYES AND SKIN. MATERIAL CAN CAUSE SKIN SENSITIZATION AND DERMATITIS.  
Effects of Overexposure:HEADACHE, DIZZINESS, TEARING OF EYES AND NOSE IRRITATION. ITCHING OF SKIN WITH SIGN OF REDNESS.  
Medical Cond Aggravated by Exposure:ASTHMA, LIVER

==== First Aid Measures =====

First Aid:EYE AND SKIN CONTACT-FLUSH EYES WITH WATER FOR AT LEAST 15 MINUTES. CONSULT PHYSICIAN. WASH SKIN WITH SOAP AND WATER.

==== Fire Fighting Measures =====

Flash Point Method:TCC  
Flash Point:>200F,>93C  
Lower Limits:NA  
Upper Limits:NA  
Extinguishing Media:FOAM, CO2, DRY CHEMICAL, WATER SPRAY  
Fire Fighting Procedures:IN CONFINED AREAS WEAR SELF-CONTAINED BREATHING APPARATUS.  
Unusual Fire/Explosion Hazard:OXIDES OF NITROGEN, MAY BE PRODUCTS OF COMBUSTION.

==== Accidental Release Measures =====

Spill Release Procedures:SCOOP UP AND RETURN TO CONTAINER. WASH AREA WITH SOAP AND WATER.  
Neutralizing Agent:ACID

==== Handling and Storage =====

Handling and Storage Precautions:STORE IN COOL DRY AREAS AWAY FROM DIRECT SUNLIGHT. KEEP IN CLOSED CONTAINERS.  
Other Precautions:AVOID CONTACT

CT WITH SKIN, EYES AND CLOTHING. WASH  
CONTAMINATED CLOTHING BEFORE RE-USE.

===== Exposure Controls/Personal Protection =====

Respiratory Protection:NIOSH APPROVED RESPIRATOR WITH ORGANIC VAPOR  
CANISTER.

Ventilation:LOCAL EXHAUST-YES. MECHANICAL (GENERAL) FAN.

Protective Gloves:RUBBER

Eye Protection:SAFETY GLASSES

Other Protective Equipment:APRON AND SAFETY SHOES.

Work Hygienic Practices:DO NOT SMOKE, DRINK OR EAT IN WORK AREAS.

Supplemental Safety and Health

KEY1:C4.

===== Physical/Chemical Properties =====

HCC:B3

Boiling Pt:B.P. Text:550F,288C

Melt/Freeze Pt:M.P/F.P Text:ROOM TEMP

Decomp Temp:Decomp Text:NA

Vapor Pres: