View NSN Online: https://aerobasegroup.co.il/nsn/8010-00-598-5460

PARKER PAINTS -- SAND #30277 -- 8010-00-598-5460

Product ID:SAND #30277 MSDS Date:07/16/1997 FSC:8010 NIIN:00-598-5460 MSDS Number: CGXLZ === Responsible Party === **Company Name: PARKER PAINTS** Address:3003 SOUTH TACOMA WAY Box:11047 City:TACOMA State:WA ZIP:98409 Country:US Info Phone Num:206-473-1122 Emergency Phone Num:800-255-3924 Preparer's Name: J. BURNWORTH

CAGE:LO231 === Contractor Identification === Company Name: PARKER PAINT Address:3003 SOUTH TACOMA WAY Box:11047 City:TACOMA State:WA ZIP:98409 Country:US Phone:253-473-1122 CAGE:9H480 **Company Name: PARKER PAINTS** Address:3003 SOUTH TACOMA WAY Box:11047 City:TACOMA State:WA ZIP:98409 Country:US Phone:206-473-1122 CAGE:LO231

Ingred Name:RULE 66 MINERAL SPIRITS (SARA 313) (VP = 2 @ 68F) CAS:8052-41-3 RTECS #:WJ8925000 Fraction by Wt: 18.0% Other REC Limits:NONE RECOMMENDED OSHA PEL:100 PPM ACGIH TLV:100 PPM

Ingred Name:NAPHTHA, HEAVY ALKYLATE(ODORLESS) (SARA 313) (VP = 2 @ 68F) CAS:64741-65-7 Fraction by Wt: 7.0% Other REC Limits:NONE RECOMMENDED OSHA PEL:100 PPM ACGIH TLV:100 PPM

Ingred Name:AROMATIC HYDROCARBON (SARA 313) (VP = 3 @ 68F) CAS:64742-95-6 Fraction by Wt: 2.0% Other REC Limits:NONE RECOMMENDED OSHA PEL:100 PPM

Ingred Name:1,2,4 TRIMETHYLBENZENE (SARA 313) CAS:95-63-6 RTECS #:DC3325000 Fraction by Wt: 0.1 8% Other REC Limits:NONE RECOMMENDED OSHA PEL:25 PPM ACGIH TLV:25 PPM

Ingred Name:ETHYLBENZENE (SARA 313) CAS:100-41-4 RTECS #:DA0700000 Fraction by Wt: 0.08% Other REC Limits:NONE RECOMMENDED OSHA PEL:100 PPM ACGIH TLV:100 PPM EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS

Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:EYE: IRRIT, RED

NESS, TEARING, BLURRED VISION. SKIN: IRRIT, DERMATITIS. INHAL: HEADACHE, NAUSEA, ASPHYXIATION, UNCONSCIOUS, NS DEPRESSION, NASAL IRRIT, CONFUSION, LIVER/KIDNEY DAMAGE. INGEST: GI IRRIT, NAUSEA, VOMIT, DIARRHEA, CHEMICAL PNEUMONITIS. First Aid:EYE: FLUSH W/WATER FOR 15 MINUTES. SKIN: WASH W/SOAP & WATER. REMOVE CONTAM CLOTHES. INHAL: REMOVE TO FRESH AIR. ARTIF RESP IF NEEDED. INGEST: DRINK 1-2 GLASSES OF WATER. DONT INDUCE VOMIT. CALL POISO N CONTROL CENTER. IN ALL CASES, GET MEDAID. Flash Point Method:SCC Lower Limits:1.0 Upper Limits:7.0 Extinguishing Media: FOAM, ALCOHOL FOAM, CO2, DRY CHEMICAL. Fire Fighting Procedures: FULL PROTECTIVE EQUIPMENT W/SCBA. USE WATER TO COOL CONTAINERS. Unusual Fire/Explosion Hazard: KEEP CONTAINERS CLOSED. KEEP FROM IGNITS. CLOSED CONTAINERS EXPLODE IN HIGH HEAT. DURING EMERGENCY CONDITIONS, OVEREXPOSURE TO DECOMP PRODUCTS MAY BE A HAZARD. Spill Release Procedures: REMOVE IGNITS. USE PROTECTIVE EQUIPMENT. CONTAIN AND REMOVE W/INERT ABSORBENT USING NON-SPARKING TOOLS. Handling and Storage Precautions: STORE IN A COOL, WELL VENTED AREA AWAY FROM IGNITS. STORE LARGE QUANTITIES IN BUILDINGS DESIGNED TO COMPLY W/OSHA 1910.1 06. Other Precautions: KEEP OUT OF REACH OF CHILDREN. Respiratory Protection: USE A PROPERLY FITTED NIOSH/MSHA APPROVED VAPOR PARTICULATE RESPIRATOR OR AIR-SUPPLIED RESPIRATOR UNLESS VENT IS ADEQUATE TO KEEP AIRBORNE CONTAM BELOW PEL/TLV LIMITS. Ventilation:SUFFICIENT VENT IN VOLUME & PATTERN W/EXPOSURE-PROOF EQUIPMENT TO KEEP CONTAM CONCENTRATIONS BELOW PEL/TLV LIMITS.

Protective Gloves: RUBBER OR NEOPRENE Eye Protec tion:CHEMICAL SAFETY GOGGLES/FULL FACE SHEILD Other Protective Equipment:USE COVERALLS & HOOD DURING SPRAY APPLICATIONS. PROTECTIVE CREAMS MAY BE USED FOR EASE OF CLEANUP, NOT FOR PROTECTION. Work Hygienic Practices:WASH HANDS BEFORE EATING AND USING RESTROOMS. Supplemental Safety and Health NK

Vapor Density:>AIR Spec Gravity:1.35 (H2O = 1) VOC Grams/Liter:3.16 Evaporation Rate & amp; Reference:SLOWER THAN ETHER Solubi lity in Water:INSOLUBLE Appearance and Odor:COLORED LIQUID, W/ALIPHATIC ODOR.

Stability Indicator/Materials to Avoid:YES STRONG OXIDIZING MATERIALS. Stability Condition to Avoid:EXTREME HEAT, SPARKS OR OPEN FLAME. Hazardous Decomposition Products:INCOMPLETE COMBUSTION CAN PRODUCE CARBON MONOXIDE.

Waste Disposal Methods:DONT ALLOW MATERIAL TO CONTAMINATE GROUND WATER SYSTEMS. ABSORB LARGE SPILLS W/SAND, CLAY, DIATOMACEOUS EARTH. DISPOSE OF IN ACCORDANCE W/FEDERAL, STATE AND LOCAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and di sclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.