View NSN Online: https://aerobasegroup.co.il/nsn/8030-01-392-2927

Product ID:OSPHO METAL TREATMENT

MSDS Date:05/01/1996

FSC:8030

NIIN:01-392-2927 Status Code:A

MSDS Number: CLNHW === Responsible Party ===

Company Name: THE SKYBRYTE CO

Address:3125 PERKINS AVE

City:CLEVELAND

State:OH

ZIP:44114-4627

Country:US

Emergency Phone Num:800-424-9300

Preparer's Name: ERNEST CA

RTER

Chemtrec Ind/Phone:(800)424-9300

CAGE:6M876

=== Contractor Identification ===
Company Name:THE SKYBRYTE CO

Address:3125 PERKINS AVE

Box:City:CLEVELAND

State:OH

ZIP:44114-4627 Country:US CAGE:6M876

======= Composition/Information on Ingredients ========

Ingred Name:PHOSPHORIC ACID

CAS:7664-38-2

RTECS #:TB6300000

= Wt:45.

OSHA PEL:1 MG/M3 ACGIH TLV:1 MG/M3 ACGIH STEL:3 MG/M3 EPA Rpt Qty:5000 LBS DOT Rpt Qty:5000 LBS

======== Hazards Identification =========

Supplemental Safety and Health

======= Physical/Che

Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:PRIMARY HAZARD LIQUID IS CORROSIVE TO EYES AND SKIN, MIST PRODUCES IRRITATION TO EYES, NOSE, THROAT, AND LUNGS. Effects of Overexposure:IRRITANT, SLIGHTLY TOXIC WHEN INHALED/INGESTED. SLIGHTLY TOXIC CAUSES BURNS TO EXPOSED TISSUE. Medical Cond Aggravated by Exposure: EMPHYSEMA, ASTHMA OR OTHER CONDITIONS RESULTING IN DECREASED RESPIRATORY FUNCTION. ======= First Aid Me asures =========== First Aid:CALL A PHYSICIAN IMMEDIATELY, INGESTION: GIVE LARGE QUANTITIES OF WATER, DO NOT INDUCE VOMITING, SKIN &EYES: FLUSH WITH WATER. ============= Fire Fighting Measures ======================== Unusual Fire/Explosion Hazard: MAY DECOMPOSE TO RELEASE OXYGEN AROUND 400C (750 F). WILL PRODUCE IRRITATING PHOSPHORIC OXIDE FUMES UNDER FIRE CONDITIONS. ======== Accidental Release Measures ============ Spill Release Proced ures:WEAR SUITABLE PROTECTION CLOTHING, EYE PROTECTION AND RESPIRATOR, NEUTRALIZE, WITH SODA ASH AND FLUSH THE AREA WITH LARGE AMOUNTS OF WATER. ============= Handling and Storage ================ Handling and Storage Precautions: USE GOGGLES AND/OR FACE SHIELDS, RUBBER APRONS, GLOVES AND BOOTS WHERE SPLASHING OR LIQUID CONTACT MAY BE EXPECTED. Other Precautions: FOR EXPOSURE TO AIRBORNE MIST USE NIOSH/MSHA ACID GAS RESPIRATORY WITH FULL FACE PIECE. KEEP STORED IN SUITABLE CONTAINER. ====== Exposure Controls/Personal Protection ======== Respiratory Protection: NIOSH/MSHA ACID GAS WITH FULL FACE PIECE. Ventilation:LOCAL EXHAUST ADEQUATE TO MEET PEL. Protective Gloves: ACID RESISTANT Eve Protection: CHEMICAL GOGGLES Other Protective Equipment: RUBBER APRON AND BOOTS AS NECESSARY. Work Hygienic Practices: STORE AND HANDLE AS STRONG ACID. WASH BEFORE EATING OR DRINKING.

mical Properties =========
Boiling Pt:=115.6C, 240.F Spec Gravity:1.22+/-04 Evaporation Rate & Description of the Solubility in Water:100% Appearance and Odor:GREEN LIQUID WITH TYPICAL ACIDIC ODOR.
========== Stability and Reactivity Data =========
Stability Indicator/Materials to Avoid:YES REACTION WITH METALS WILL LIBERATE HYDROGEN GAS. (EXTREMELY FLAMMABLE!) Stability Condition to Avoid:AVOID CONTACT WITH STRONG ALKALIES. WITH METALS. Hazardous Decomposit ion Products:PHOSPHORIC ACID FUMES. (STRONG IRRITANT) Conditions to Avoid Polymerization:WILL NOT OCCUR.
Disposal Considerations

Waste Disposal Methods: NEUTRALIZE WITH SODA ASH OR LIME AND DISCHARGE INTO A TREATMENT SYSTEM IN ACCORDANCE WITH LOCAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.